

Audi / VW 2.7tdi & 3.0tdi Inlet Manifolds x2 - Type B.



Audi / VW 2.7tdi & 3.0tdi Inlet Manifolds Type B

Audi / VW / Porche 2.7TDI & 3.0TDI Inlet Manifold Remanufactured
[exchange]
6 month warranty.

Left Hand side: 059 129 711 BQ / 059 129 711 CG / 059 129 711 AF / 059 129 711 AL / 059 129 711 CK / 059 129 711 T / 059 129 711 BR / 059 129 711 BS / 059 129 711 AR / 059 129 711 CH / 059 129 711 BK / 059 129 711 CL

Right Hand side: 059 129 712 BE / 059 129 712 BL / 059 129 712 T / 059 129 712 BQ / 059 129 712 BK / 059 129 712 H / 059 129 712 BM / 059 129 712 BN / 059 129 712 BG / 059 129 712 AJ / 059 129 712 CK / 059 129 712 BS / 059 129 712 BR / 059 129 712 BF

A common fault with Audi & VW 2.7tdi and 3.0tdi engines, unfortunately when the inlet manifold wears it brings the engine management light on,

warning that there is a fault, it will bring up the following codes on the engine diagnostic.

P2008 - Intake Manifold Runner Control [Bank 1] / P2011 - Intake Manifold Runner Control [Bank 2] / 004120 - [Bank 2] Lower limit not reached / P1018 - 001 - Upper lower limit exceeded / 012597 - Intake Manifold Runner Control lower stop not reached / P3135 - 001 - lower limit exceeded.

Fits the following models and engines:

Models: Audi – A4, A6, A8, Q7, Allroad / VW – Toureg & Phaeton **Engine Codes:** ASB, BNG, BKN, BPP, BUN, BUG, BKS. When ordering please supply us with your vin / chassis number so we can insure you have the correct parts for your vehicle Next day UK delivery before 1pm providing we have your order before 3pm on the day of purchase. [not including weekends]

Audi / VW 2.7tdi & 3.0tdi Inlet Manifolds x2 Type B are sold on an exchange basis.